



The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Representatives Present During the Inspection:							
	Company	Dennis Oakley					
	OGM	Steve Demczak					

Inspection Report

Permit Number:	C0150017
Inspection Type:	PARTIAL
Inspection Date:	Monday, April 18, 2011
Start Date/Time:	4/18/2011 10:00:00 PM
End Date/Time:	4/18/2011 2:00:00 PM
Last Inspection:	Monday, March 14, 2011

Inspector: Steve Demczak,
Weather: Cloudy, Windy, 40's
InspectionID Report Number: 2716

Types of Operations

Accepted by: jhelfric

5/3/2011

Permitee: **ENERGY WEST MINING CO**Operator: **ENERGY WEST MINING CO**

Site: **DES BEE DOVE MINE**

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Total Permitted	133.90
Total Disturbed	40.90
Phase I	136.58
Phase II	95.70
Phase III	95.70

Mineral Ownership

✓ Federal
✓ Underground

State
Surface

County
Loadout

✓ Fee
Processing

Other
Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

iteve Demczak,

Date

Monday, April 18, 2011

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Inspection Continuation Sheet

Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Monday, April 18, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	~		✓	
2.	Signs and Markers	✓		✓	
3.	Topsoil	~		✓	
4.a	Hydrologic Balance: Diversions	✓		~	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		V		
4.c	Hydrologic Balance: Other Sediment Control Measures	V		V	
4.d	Hydrologic Balance: Water Monitoring		✓		
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments		V		
8.	Noncoal Waste	✓		V	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	V		✓	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	V		✓	
13.	Revegetation	✓		V	
14.	Subsidence Control				
15.	Cessation of Operations	V		V	
16.8	Roads: Construction, Maintenance, Surfacing				
16.t	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓		~	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Monday, April 18, 2011

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

No permitting action with the Division. The Division is reviewing the Annual Report.

2. Signs and Markers

The identification signs is located on the trail to the mine site.

3. Topsoil

All topsoil was used in reclamation.

4.a Hydrologic Balance: Diversions

Diversions were spot-checked and would function in a storm event. There were no signs of water erosion to the diversion.

4.c Hydrologic Balance: Other Sediment Control Measures

There is one area North Facing that erosion has started to occur. The slopes are steep in this area. A diversion ditch is adjacent to area of erosion. This area should be watched. This erosion area is above the water channel and sediment could enter the channel and go off site.

8. Noncoal Waste

The area was clear of non-coal waste material.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

12. Backfilling And Grading

The site is backfilled and graded to AOC standards in my opinion.

13. Revegetation

It's to early to see vegetation growing at this time.

15. Cessation of Operations

The site is completely reclaimed.

18. Support Facilities, Utility Installations

There are no facilities at this site.